

Index

• Numerics •

- 1.5-sigma shift, 192–195
 - 2^k factorial experiments
 - analyzing
 - effects, 270–276
 - equation, 276–278
 - overview, 270
 - conducting
 - blocking, 269
 - gathering data, 269–270
 - overview, 269
 - randomizing, 269
 - planning
 - experiment factors, 266–267
 - experimental codes and design matrix, 267–268
 - overview, 266
 - 3-Gen approach (going to *gemba*), 98, 109, 350
 - 5S method, 285–287, 351
 - 80-20 rule, 40
- ## • A •
- absolute values, 128
 - academic training, 356
 - acceptance handling, 324
 - accountability, 13
 - accuracy, 201–202
 - achievability, 20
 - actions, improvement, 111
 - actuals, 339
 - adjusted long-term capability (P_{PK}) indices, 195, 198
 - adjusted short-term capability indices (C_{PK}), 195–198
 - affinity diagrams, 70, 102, 314
 - AIAG (Automotive Industry Action Group), 107–110

- alignment, 338
 - alpha (α) risk, 232
 - American Society for Quality (ASQ), 354
 - American Statistical Association (ASA), 354
 - analysis of variance (ANOVA), 279
 - analytics
 - calculators, 324–325
 - computers, 325
 - manual computations, 324
 - Analyze step, 44, 66–67
 - andons, 333
 - ANOVA (analysis of variance), 279
 - Apple iWork, 316
 - approval, project, 85–86
 - ASA (American Statistical Association), 354
 - as-is state, 92, 97–98
 - ASQ (American Society for Quality), 354
 - assignments, project, 85–86
 - associations, 354
 - attainability, 20
 - attribute (category) data
 - control charts, 292, 305–308
 - description, 114–115
 - measurement system studies, 204–207
 - audits, 203–204
 - Automotive Industry Action Group (AIAG), 107–110
 - average. *See* mean
 - averages and ranges ($X - R$) charts, 292, 301, 303–304
 - averages and standard deviations ($X - S$) charts, 292, 301, 304
- ## • B •
- balanced scorecards, 340–342
 - Bank of America, 12
 - baselines
 - description, 74–75
 - modeling, 92
 - plans, 340

- batch processing, 160
 - behavior, 26–30
 - behavior charts. *See* process behavior charts
 - belief systems, 26–30
 - believability, 20
 - bell-shaped variation, 165–173
 - belt terminology
 - Black Belts
 - problem difficulty distribution, 86
 - project management, 332
 - responsibilities, 55, 351–352
 - role relationship map, 52
 - spreadsheets and, 325–326
 - Green Belts, 52, 54–56, 86, 351–352
 - Master Black Belts, 55, 86, 351–352
 - overview, 54–55
 - unleashing potential, 347
 - Yellow Belts, 54, 56, 86, 352
 - benefits, project, 337
 - β s (coefficients), 277–278
 - between group variation, 214–215
 - between unit variation, 216, 220–221
 - beyond control limits, 298
 - Black Belts
 - problem difficulty distribution, 86
 - project management, 332
 - responsibilities, 55, 351–352
 - role relationship map, 52
 - spreadsheets and, 325–326
 - blocking, 269
 - boil-the-ocean approach, 263–264
 - books, 355
 - boutiques, 356
 - box and whisker plots
 - custom, 141–143
 - interpreting, 143–144
 - box scores, 98–99
 - boxes, 141
 - BPM (business process management), 320–321, 327
 - BPMN (Business Process Modeling Notation) standard, 89
 - brainstorming tools
 - affinity diagrams, 70, 102, 314
 - fishbone (Ishikawa) diagrams, 102–103, 314
 - breakthrough
 - designing for, 45–47
 - managing for, 45, 47
 - processing for, 45–46
 - thinking for, 45–46
 - breakthrough equation ($Y = f(X) + \epsilon$), 31–32, 277–278
 - breakthrough improvement, 12, 82–83
 - buckets, 305
 - business cases, 68–70
 - business process management (BPM), 320–321, 327
 - Business Process Modeling Notation (BPMN) standard, 89
 - business unit deployment leaders, 53
- C •
- C&E analysis. *See* cause-and-effect analysis
 - calculators
 - hand-held, 324
 - online, 324–325
 - capability
 - belief system and, 26
 - calculating online, 324
 - defect rate, 184–189
 - indices, 195–198
 - overview, 179
 - short-term, 192–195
 - sigma (Z) score, 189–195
 - yield, 179–184
 - capture, process, 319
 - category data. *See* attribute data
 - causation, 34–35, 223–224, 246
 - cause and effect, 33–34, 108
 - cause-and-effect (C&E) analysis
 - group input, 164
 - matrix, 161–162
 - overview, 161
 - score, 162–163
 - weight, 162
 - centerlines, 293
 - central limit theorem, 228–229
 - central tendency, 118–119
 - Champions, 53, 332, 351–352
 - change management, 333

- changeover times, 99
- characteristic behavior charts. *See* process behavior charts
- characteristic performance distribution, 190
- characterizing
- experiments, 265
 - process, 319
- charts. *See* graphical analysis; *names of specific charts*; process behavior charts
- chi factor (χ^2 factor), 235
- closed-loop behavior, 92
- clusters, 69–70
- Coca-Cola Company, 17–18
- coded design matrix, 268, 270
- coded setting values, 271–273
- coefficient of determination (R^2), 253
- coefficients (β s), 277–278
- colleagues, 353
- commitment, top, 13
- common cause variation, 36–37, 127, 296
- communication, leadership and, 332, 334
- communications plan, 57
- communications representatives, 51
- complaints, 185
- complexity, 183–184
- computers. *See also* technology tools
- desktop
 - Microsoft Office, 316–317
 - overview, 313
 - process mapping, 317–318, 320–321 - laptop, 313
 - programs and utilities for Six Sigma, 325
- conferences, 355
- confidence intervals
- for means, 230–234
 - overview, 230
 - for proportions, 237–239
 - for standard deviations, 234–237
- confounding (outside) variables, 34
- consistency, 26, 37
- constant terms, 277
- consultants, 355–356
- continuous (variable) data, 113–116, 291–292, 300–304
- continuous variable measurement system studies, 207–208
- control charts
- for attribute data, 305–308
 - collecting data, 300
 - for continuous data, 300–304
 - control limits, 294–296
 - keeping process on track, 296–297
 - monitoring, 293–294
 - overview, 291–293
 - patterns, shifts, and drifts, 297–300
- control limits, 294–296
- control planning, 65, 281–284, 288
- Control step, 44, 66–67
- controls
- calculating online, 324
 - identifying current, 109
 - methods, 224
 - project definition, 337
 - scoring detection, 109–111
- conventions, drawing, 89–90
- core teams, assembling, 49–50
- corporations, 354
- correlation coefficient (r), 244–245
- correlations
- calculating, 243–246
 - causation versus, 34–35
 - drawing from scatter plots, 146–150
- cost avoidance, 76
- cost improvements, 75
- costs
- of poor quality, 25
 - of resources consumed, 91
- count (frequency), 136
- C_p (short-term capability indices), 195–196
- C_{PK} (adjusted short-term capability indices), 195–198
- critical few
- narrowing data, 210–211
 - separating and utilizing, 41–42
 - trivial many and, 40–41
- critical-to (CT) trees, 314
- critical-to-quality outputs (CTQs), 282
- culture change, 16
- curvature, 278

- curve fitting
 - linear regression, 247–249, 254–257
 - overview, 246–247
 - residuals and, 249–254
 - customer value
 - ascertaining, 156
 - Kano's framework, 158–160
 - overview, 155–156
 - value add processes, 349
 - waste, 157–158
 - customers
 - considering, 97
 - definition, 93
 - focus on, 13
 - cycle times
 - for process elements, 90
 - versus takt time, 98–99
 - cycles, 300
 - cyclical variation, 216, 220–221
- **D** •
- dashboards, 333, 340–341
 - data. *See also* attribute data; continuous data
 - gathering, 210–211, 269–270, 300
 - measuring, 39
 - overview, 113
 - querying, 210–211
 - statistics, 116–124
 - trusting, 346
 - types, 113–116
 - variation, 125–131
 - data entry, 315
 - Data icon, 90
 - data mining
 - filling funnel
 - gathering and querying data, 210–211
 - overview, 209
 - graphical analysis
 - example, 213–215
 - interaction effects plots, 215
 - main effects plots, 215
 - multi-vari studies, 215
 - multi-vari charts
 - categorizing variations, 216–217
 - example, 223–226
 - interpreting, 220–222
 - new, 218–220
 - sampling plan, 217–218
 - observational studies
 - description, 212–213
 - recording data, 211–212
 - data points, 244–245, 294
 - Decision icon, 90
 - decision-making
 - central limit theorem, 228–229
 - confidence intervals, 230–239
 - populations and samples, 227–228
 - with samples, 231–233
 - defect rate
 - DPMO, 188–189
 - DPO, 187–188
 - DPPM, 185
 - DPU, 186
 - failure, 185–186
 - linking yield and, 189
 - overview, 184–185
 - sigma scores, 194–195
 - defective parts per million (DPPM), 185
 - defectives, 305–307
 - defects
 - control charts, 305–308
 - levels, 74
 - preventing with Poka-Yoke, 287–288
 - sigma scale, 28–29
 - waste, 157
 - defects per million opportunities (DPMO), 185, 188–189, 194
 - defects per opportunity (DPO), 185, 187–188
 - defects per unit (DPU), 185, 186
 - Define, Measure, Analyze, Improve, Control (DMAIC) method, 43–45
 - Define step, 44, 63, 66–67
 - definition tools, 335
 - delighters, 159
 - Deming, W. Edwards, 47
 - Deming cycle, 351
 - deployment leaders, 51–53
 - deployment stage, 58
 - Design for Six Sigma (DFSS), 46–47
 - design matrices, 267–268

- Design of Experiments. *See* DOE
- designing for breakthrough, 45, 46–47
- desktop computers
- Microsoft Office, 316–317
 - overview, 313
 - process mapping, 317–318, 320–321
- detection scoring scale, 110–111
- determinism
- cause and effect, 33–34
 - resisting superstitious delusions, 34–35
- deterministic situations, 246–247, 265
- deviations
- bell-shaped variation, 166–167
 - characteristic performance
 - distribution, 190
 - population, 235–237
 - qualifying variations in terms of, 253
 - short-term, 128
 - for small samples, 232
 - standard, 121–124, 190–191
- DFSS (Design for Six Sigma), 46–47
- diagramming
- brainstorming tools
 - affinity diagrams, 70, 102, 314
 - fishbone (Ishikawa) diagrams, 102–103, 314
 - failure mode effects analysis
 - calculating and reviewing risk priority number scores, 111
 - controls, 109–111
 - devising and assigning improvement actions, 111
 - effects of failures, 106–108
 - failure modes, 106, 108–109
 - listing process steps, 104–106
 - overview, 103–104
- difference of proportions, 239
- distribution. *See also* standard
- normal distribution
 - adjusted short-term capability index, 197
 - calculating online, 324
 - in comparative box plots, 143–144
 - control charts, 293–294
 - description, 117–118
 - location, 118–120
 - multi-modal, 138–139
 - nonstandard, 171–172
 - normal, uniform, and skewed, 137–138
 - sampling, 229
 - sigma (Z) score, 191
 - skewed, 137–138
 - disturbances to the process, 128–129
 - DMAIC (Define, Measure, Analyze, Improve, Control) method, 43–45
 - Docs, Google, 316
 - Document icon, 90
 - documents
 - management, 340
 - reading with Microsoft Office, 316
 - DOE (Design of Experiments)
 - ANOVA, 279
 - approaches, 262–265
 - curvature, 278
 - fractional factorial experiments, 279
 - improvement with, 259–262
 - overview, 259
 - replications, 278
 - response surface methods and optimization, 279
 - robustness, 279
 - 2^k factorial, 266–278
 - domains of activity
 - designing for breakthrough, 46–47
 - managing for breakthrough, 47
 - processing for breakthrough, 46
 - thinking for breakthrough, 45–46
 - dot plots, 136–140
 - DPMO (defects per million opportunities), 185, 188–189, 194
 - DPO (defects per opportunity), 185, 187–188
 - DPPM (defective parts per million), 185
 - DPU (defects per unit), 185, 186
 - drawing conventions, 89–90
 - drifts, 297–300
 - Dupont, 12
- **E** ●
- e (constant), 189
 - EBIT (Earnings Before Income Tax), 64

effects
 of failures, 106–108
 interaction, 256, 272–274
 main, 256, 270–272
 overall and second-order, 256
 significant, 274–276
 80-20 rule, 40
 e-mail, 334
 enterprise service bus (ESB), 333
 enterprise-class technology, 313–314, 321
 entitlement, 80–81, 130–131
 entitlement level
 definition, 46
 of performance, 81, 279
 entitlement variation. *See* short-term variation
 ϵ . *See* error
 equations
 breakthrough, 31–32, 277–278
 general, 276–277
 equipment
 breakdown of, 131
 maximizing availability of, 99
 error (ϵ)
 definition, 32, 123
 exposing hidden, 24
 risk, 42
 summed square error, 252–253
 ESB (enterprise service bus), 333
 evaluation, 338
 Excel, Microsoft, 172–173, 326
 executive dashboards, 341
 executives, 48–49
 expansion stage, 59–60
 expectations, 35
 experiments. *See also* 2^k factorial experiments; DOE
 design matrix and codes, 267–268
 factors, 266–267
 versus observational studies, 212–213
 external forces, 131
 extra processing, 157

● F ●

f (function), 31–32
 F tests, 253

F values, 236–237
 factorial experiments. *See* 2^k factorial experiments
 factors, DOE, 261
 fails, 205–206
 failure mode effects analysis. *See* FMEA
 failure modes, 104, 106–109
 failures
 defects, 185–186
 effects, 106–108
 finance representatives, 50
 financial guidelines, 57
 financial measures, 345
 first quartile, 142
 first time yield (FTY), 180–182
 fishbone (Ishikawa) diagrams, 102–103, 314
 5S method, 285–287, 351
 flat files, 317
 flow, 99, 350
 flowcharting software, 317–318, 320–321
 FMEA (failure mode effects analysis)
 calculating and reviewing risk priority number scores, 111
 controls, 109–111, 288
 devising and assigning improvement actions, 111
 effects of failures, 106–108
 failure modes, 106, 108–109
 leveraging for value, 164
 listing process steps, 104–106
 overview, 103–104
 football example, 23–25
 Ford, Henry, 12
 Ford Motor Company, 22
 Ford Probe, 22
 fractional factorials, 266, 279
 frequency (count), 136
 FTY (first time yield), 180–182
 function (f), 31–32
 functional representatives, 50–51

● G ●

Galvin, Robert, 14
 Gantt project schedules, 339
 gauge studies, 207–208
gemba, 98, 109

- genchi genbutsu*, 98, 350
 General Electric, 12
genjitsu, 350
 goals, 84, 346–347
 going to *gemba* (3-Gen approach),
 98, 109, 350
 Google Docs, 316
 graphical analysis. *See also* control charts
 affinity diagrams, 70
 averages and ranges, 292, 303–304
 averages and standard deviations,
 292, 304
 bell-shaped variation, 165
 box and whisker plots, 141–144
 cause-and-effect matrix, 161–163
 of characteristics, 21, 190
 confidence intervals, 231, 234
 control charts, 295, 298
 distribution, 197, 294
 dot plots, 136–140
 effective width, 196
 failure mode effects analysis, 103–111
 first time yield, 181
 hidden factory, 182
 histograms, 136–140, 294–295
 individual values and moving ranges,
 292, 302–303
 interaction effects, 274
 macro process maps, 73
 main effects plots, 150, 271–272
 of mean and median, 120
 multi-vari charts, 219–226
 non-normal behavior, 152
 non-random disturbances, 129
 non-value added process steps, 158
 normal probability plots, 174–177, 276
 overview, 135
 p charts, 292, 306–307
 possible variables and key outputs,
 214–215
 probability distributions, 129–130
 process behavior charts, 150–154
 process maps, 88, 91–92
 residual plots, 250–252
 runs, 154
 samples, 229
 scatter plots, 144–150, 254–255
 shifts, 154
 simple linear regression, 248
 standard normal probability table,
 167–171
 time scales, 117–118
 time-series charts, 74
 traditional yield, 180
 trends, 153
 u charts, 292, 307–308
 value stream maps, 94–99
 variation, 125–127, 193, 213–215
 Green Belts, 52, 54–56, 86, 351–352
 group input, 164, 332, 351
 group members. *See* team members
- H •
- hand-held calculators, 324
 hard savings, 75
 help resources
 associations, 354
 books, 355
 colleagues, 353
 conferences, 355
 consultants, 355–356
 corporations, 354
 social networks, 353–354
 societies, 354
 technology vendors, 355
 trainers, 356
 web searches, 353–354
 hidden factory, 24–25, 81–82, 182
 histograms, 136–140, 294–295
 Honeywell, 12
 hugging, 300
 human resources (HR), 51, 57
- I •
- I* – \overline{MR} (individual values and moving
 ranges) charts, 292, 301–303
 icons, mapping, 90
 idealistic measures, 192
 ideation, 335–336

- implementation stage, 58–59
 - improvement
 - actions, 111
 - belief system and, 26
 - breakthrough, 12
 - control planning, 281–284, 288
 - DMAIC, 44, 66–67
 - experiments, 278–279
 - 5S method, 285–287
 - by managers, 352
 - mindset, 352
 - mistake-proofing with Poka-Yoke, 287–288
 - opportunities, 99
 - overview, 281
 - standards, 289
 - target amount for project, 80–83
 - in spec, 21
 - independence, 124
 - indices. *See* capability; graphical analysis
 - individual values and moving ranges
 - ($I - \overline{MR}$) charts, 292, 301–303
 - information flow, 99
 - information technology (IT), 51, 58
 - infrastructure, 15–16
 - initialization stage, 57–58
 - initiatives, 56–60
 - input, team
 - cause-and-effect analysis, 164
 - involving right people in project, 332
 - Lean practices, 351
 - value stream maps, 97
 - input forms, 315
 - inputs
 - breakthrough equation, 31–32
 - cause-and-effect matrix, 161–163
 - critical few, 41–42
 - definition, 93
 - determinism, 33–34
 - entitlement level of performance, 81
 - fishbone diagrams, 103
 - narrowing field, 210–211
 - plotted against outputs, 145, 149
 - possible variables, 213–215
 - process control plans, 283
 - recording, 212
 - relationship between outputs and, 260–262
 - residuals versus observed, 251
 - 2^k factorial experiments, 266
 - Inspection icon, 90
 - inspection measurement systems, 204–205
 - Inspection step, 81–82
 - instructions, handwritten, 315
 - intelligence tools, 340–342
 - interaction effects, 215, 256, 272–274
 - International Society of Six Sigma Professionals (ISSP), 354
 - inventory
 - decreasing, 99
 - waste, 157
 - Ishikawa (fishbone) diagrams, 102–103, 314
 - Ishikawa, Kaoru, 102
 - iSixSigma forum, 354
 - ISSP (International Society of Six Sigma Professionals), 354
 - IT (information technology), 51, 58
 - iWork, Apple, 316
- **J** •
- JMP products, 329
- **K** •
- kaizen*, 351–352
 - Kano, Noriaki, 158
 - Kano's framework, 158–160
 - key goals, 346–347
 - Key Performance Indicators (KPIs), 64
 - knowledge management (KM) tools, 333, 342
- **L** •
- laptop computers, 313
 - largest observed value (x_{MAX}), 121, 142–143
 - launch planning, 57
 - layouts, 99
 - LCLs (lower control limits), 293
 - leadership, 47–48, 332, 347

- Lean methodology
 - customer value, 349
 - 5S method, 351
 - flow, 350
 - improvement, 352
 - muda-mura-muri* (waste), 350–351
 - practices, 59
 - simplicity, 351
 - team input, 351
 - 3-Gen approach (going to *gemba*), 350
 - value stream maps, 350
 - learning tools, 333
 - left-hand probability, 173
 - letters, 334
 - levels, DOE, 261
 - leverage, 39–42
 - limits, 196
 - linear regression
 - multiple, 255–257
 - simple, 247–249, 254–255
 - linearity, 202, 244–246
 - ln (natural logarithm), 189
 - location, of distribution, 118–120
 - long-term calculations, 191–192
 - long-term capability (P_p) indices, 195, 198
 - long-term performance, 192–195
 - long-term variation
 - computing, 130
 - non-random behavior, 129–130
 - overview, 128–129
 - shift, 128–130
 - short-term variation and, 27–28, 37–38, 125, 131
 - Lord Kelvin (William Thompson), 116–117
 - Lotus 1-2-3, 326
 - lower control limits (LCLs), 293
 - lower specification limits (LSLs), 19, 21
 - low-hanging fruit, 60
 - LSLs (lower specification limits), 19, 21
- M •**
- machine operators, 131
 - macro process maps, 73
 - macros, 326
 - magnitude of problems, 74, 79
 - main effects
 - calculating, 270–272
 - plots, 150, 215
 - terms, 256
 - management
 - commitment, 13
 - dashboards, 58
 - executives and, 48–49
 - functional, 332
 - improvement by, 352
 - objective statements and, 84–85
 - perspective, 11–16
 - project definition, 337
 - responsibilities, 48–49
 - review process, 16
 - managing for breakthrough, 45, 47
 - manual tools, 312–315, 324
 - mapping. *See also* value stream maps
 - with Microsoft Visio, 317–318
 - overview, 87, 320–321
 - process, 88–92
 - SIPOC, 93–94
 - value stream maps, 94–99
 - mapping icons, 90
 - Master Black Belts, 55, 86, 351–352
 - master standards, 205–206
 - matrices
 - cause-and-effect, 161–162
 - design, 267–268, 270
 - tables and, 315
 - Mazda MX-6, 22
 - mean (average)
 - bell-shaped variation, 166
 - calculating, 119–120
 - characteristic performance
 - distribution, 190
 - comparing, 233–234
 - confidence intervals, 230–234, 239
 - for control charts, 293
 - definition, 36
 - simple linear regression, 249
 - for units, 219–220
 - variation average, 140
 - measurability, 20

- Measure step, 44, 66–67
 - measurement
 - accuracy of, 201–202
 - confidence, 230
 - with data, 39
 - multi-vari charts, 219
 - output and input, 38–39
 - overview, 38
 - precision of, 202–203
 - resolution of, 201
 - Measurement System Analysis. *See* MSA
 - median, 119, 120, 142
 - memos, 334
 - metrics, 13
 - Microsoft Excel, 172–173, 326
 - Microsoft Office
 - overview, 316
 - presentation packages, 317
 - reading documents, 316
 - spreadsheets, 316–317
 - Microsoft Project, 339
 - Microsoft Visio, 317–318
 - mining data. *See* data mining
 - Minitab package, 328
 - mistake-proofing, 287–288
 - mode, 119, 138–139
 - modeling processes, 92
 - monitoring, 293–294
 - motion, 157
 - Motorola, 12, 14, 54
 - moving range charts, 302–303
 - MSA (Measurement System Analysis)
 - methods, 203–208
 - overview, 199
 - variation in, 200–203
 - muda*, 350–351
 - muda-mura-muri* (waste), 350–351
 - multi-modal distribution, 138–139
 - multiple linear regression, 247, 255–257
 - multitasking, 264–265
 - multi-vari charts
 - categorizing variations, 216–217
 - description, 215
 - example, 223–226
 - interpreting, 220–222
 - new, 218–220
 - overview, 216
 - sampling plan, 217–218
 - mura*, 350–351
 - muri*, 350–351
- *N* •
- natural logarithm (\ln), 189
 - needs, 159
 - Net Profit Before Income Tax (NPBIT), 64
 - nodes, 90
 - non causa pro causa*, 34
 - non-conformities per unit (u) charts, 292, 305
 - non-normal behavior, 151–152, 177
 - non-random behavior, 129–130
 - non-value added (NVA) process steps, 91, 98, 156, 158
 - normal behavior, 150–152
 - normal distribution, 137, 191
 - normal probabilities, 172–173
 - normal probability plots, 174–177, 276
 - normal score. *See* sigma score
 - normally-shaped variation
 - bell-shaped, 165–173
 - normal probability plots, 174–177
 - NORMDIST(x, x, s, I) formula, 173
 - NORMINV(probability, x, s) formula, 173
 - NORMSDIST(z) formula, 173
 - NORMSINV(probability) formula, 173
 - NPBIT (Net Profit Before Income Tax), 64
 - nuisance factors, 32, 269
 - NVA (non-value added) process steps, 91, 98, 156, 158
- *O* •
- objectives
 - demonstrating, 74
 - linking projects to, 84
 - project definition, 336
 - setting, 80
 - statements, 83–85

- observational studies
 - description, 212–213
 - versus experiments, 260
 - overview, 211
 - recording data, 211–212
 - occurrence scoring scale, 108
 - Office suite. *See* Microsoft Office
 - offset terms, 277
 - 1.5-sigma shift, 192–195
 - one-factor-at-a-time approach, 263
 - one-sided specifications, 18
 - online calculators, 324–325
 - online training, 356
 - Op *i*, 81
 - Open Source OpenOffice, 316
 - opportunities, 187–189
 - optimization, RSM and, 279
 - optimization experiments, 265, 279
 - ordinal data, 115
 - organizing
 - DMAIC method, 43–45
 - domains of activity, 45–47
 - roles, 48–56
 - stages of initiative, 56–60
 - out of control, 41
 - outliers, 120–122, 140, 152–153
 - outputs
 - along time scales, 117–118
 - breakthrough equation, 31–32
 - cause-and-effect matrix, 161–163
 - definition, 93
 - determinism, 33–34
 - entitlement level of performance, 81
 - fishbone diagrams, 102–103
 - graph of behavior over extended period, 125–127
 - identifying significant, 73
 - for improvement, 73
 - inputs and, 38–39, 145, 149, 260–262
 - key, 213–215
 - recording, 212
 - variation, 36, 129
 - outside (confounding) variables, 34
 - overall effects, 256
 - overproduction, 157
 - overtraining, 348
- *p* ●
- p* (proportion nonconforming) charts, 292, 305–308
 - paired data, 243–244, 268
 - Pareto, Vilfredo, 40, 204
 - Pareto diagrams, 204
 - Pareto principle, 266
 - passes, 205–206
 - patterns, 297–300
 - PDCA (Plan-Do-Check-Act) cycle, 351
 - performance
 - description of Six Sigma, 9–11
 - entitlement level, 81
 - forecasting, 243–258
 - long-term, 192–195
 - managerial perspective, 11–16
 - perspective, 92
 - phone calls, 334
 - pi (π), 183
 - PI (Process intelligence), 318–319, 333, 340
 - Plackett-Burman experiment designs, 266–267
 - Plan-Do-Check-Act (PDCA) cycle, 351
 - planning, 346
 - platforms
 - desktops and laptops, 313
 - enterprise-class technology, 313–314
 - manual tools, 312–313
 - overview, 312
 - smartphones and tablets, 313
 - plots. *See* graphical analysis
 - pocket calculators, 324
 - Poka-Yoke, 287–288
 - populations
 - samples and, 227–228
 - standard deviation, 235–237
 - positional variations, 216–217, 220–221
 - potential
 - savings, 75
 - unleashing, 347
 - value, 76
 - PowerPoint, 317
 - P_p (long-term capability) indices, 195, 198

- P_{PK} (adjusted long-term capability) indices, 195, 198
- practical problems and solutions, 65
- precision, 202–203
- predictions, 248, 250
- presentations, 317, 334
- principles of Six Sigma
 - breakthrough equation, 31–32
 - determinism, 33–35
 - leverage, 39–42
 - measuring, 38–39
 - reducing variation, 35–38
 - risk management, 42
- prioritizing, 338
- probability
 - bell-shaped variation and, 165–173
 - control limits and, 294–295
 - formulas, 173
 - quality and, 27
- probability distribution (probability density function)
 - bell-shaped variation, 166–167
 - definition, 118
 - interaction effects, 275
 - long-term and short-term process variation, 129–130
 - patterns, shifts, and drifts, 297
 - standard normal, 167–171
- problem statements, 77–79
- process behavior charts, 150–154
- process capability, 324
- process capture, 319
- process characterization, 319
- process control plans, 281–282
- process flow, 160–161
- Process icon, 90
- process intelligence (PI), 318–319, 333, 340
- process mapping
 - acknowledging as-is state, 92
 - drawing process map, 89–90
 - manual tools and, 315
 - with Microsoft Visio, 317–318
 - overview, 88–89
 - process points, 90–92
 - SIPOC, 94
 - swim lanes, 91–92
- process monitoring, 282
- process orientation, 13–14
- process outputs, 73
- process owners, 85–86
- process points, 90–92
- process steps
 - capturing, 97–98
 - listing, 104–106
 - rolled throughput yield, 183–184
- process timeline, 98
- processes, SIPOC, 93
- processing
 - for breakthrough, 45–46
 - extra, 157
- production flow, 160–161
- progressing, 264–265
- Project, Microsoft, 339
- project definition, 336–337
- project focus, 14
- project management
 - communicating, 334
 - involving right people, 332
 - overview, 331
 - tools, 332–333, 335–340
- project selection
 - alignment, 338
 - evaluation, 338
 - overview, 337
 - priority, 338
- projects
 - aligning, 66, 346–347
 - approval and assignment, 85–86
 - defining, 70–76
 - launching, 64–67
 - lifecycle of, 65
 - map of Six Sigma activity, 52
 - objective statements, 83–85
 - overview, 63, 77
 - problem statements, 77–79
 - responsibility and ownership, 67
 - scoping, 347–348
 - selection guidelines, 57
 - target amount of improvement, 80–83
 - tracking and reporting, 58
 - writing business case, 68–70

proportion nonconforming (p) charts,
292, 305–308

proportions

confidence intervals, 237–239
difference, 239

protocols. *See* platforms

purposes, 336

• Q •

quadruplets, 268

quality

behavior determined by belief systems

calculating Six Sigma quality, 28–30

comparing, 26

connecting quality and variation, 27–28

overview, 26

rolled throughput yield, 27

definition

avoiding hidden factory, 25

cost of poor quality curve, 23–25

overview, 20–23

specifications

definition, 18–19

need for, 18

overview, 17–18

RUMBA, 19–20

quantifiable metrics, 338

quartile values, 142

• R •

r (correlation coefficient), 244–245

R (range), 121–122, 127–128, 140

R^2 (coefficient of determination), 253

random variables, 256

randomizing, 269

range (R), 121–122, 127–128, 140

rank order data, 115, 176

ratio of variances, 239

rational subgroups, 300

raw materials, 131

Realize step, 66

Reasonable, Understandable, Measurable,
Believable, Attainable (RUMBA) test,
19–20

reasonableness, 20

Recognize step, 66

relationships, 146–150, 162, 260–262. *See*
also correlation coefficient

repeatability, 202–203, 206

repetitions, 229

replication, DOE, 261

replications, 278

reporting, 335, 339

reproducibility, 202–203, 206

residuals

curve fitting and, 249–254

in multiple linear regression model, 256

resolution, 201

response, DOE, 261

response surface methods (RSM), 279

responsibilities, project, 67

results, 65, 345–346

return on investment (ROI), 13

rework, 24, 182

rise, 149

risk, 337

risk management, 42

risk priority number (RPN) scores, 104, 111

robustness, 279

ROI (return on investment), 13

roles

Black Belts, 55

problem difficulty distribution, 86

project management, 332

responsibilities, 55, 351–352

role relationship map, 52

spreadsheets and, 325–326

Champions, 53, 332, 351–352

core team, 49–50

deployment leader, 51–53

executives and managers, 48–49

functional representatives, 50–51

Green Belts, 52, 54–56, 86, 351–352

hierarchy, 55

Master Black Belts, 55, 86, 351–352

- roles (*continued*)
 - overview, 48, 54–55
 - relationships, 52
 - Yellow Belts, 54, 56, 86, 352
 - rolled throughput yield (RTY), 27, 180, 183–184
 - Royal Statistical Society (RSS), 354
 - RPN (risk priority number) scores, 104, 111
 - RSM (response surface methods), 279
 - RSS (Royal Statistical Society), 354
 - RTY (rolled throughput yield), 27, 180, 183–184
 - RUMBA (Reasonable, Understandable, Measurable, Believable, Attainable) test, 19–20
 - run order, 150
 - runs
 - Design of Experiments, 261
 - overview, 153–154
 - ratio of rises to, 149
- S •
- SaaS (Software as a Service), 314
 - Saint John's University, 325
 - samples
 - data, 296
 - populations and, 227–228
 - sampling distribution, 229
 - SAS Institute, 329
 - savings, 75
 - Sayer, Natalie, 349
 - scatter plots
 - developing, 144–145
 - drawing correlations from, 146–150, 243–245
 - fitting lines, 254–255
 - schedules, 337, 339
 - scoping projects, 347–348
 - scoring
 - balanced scorecards, 340–342
 - calculating and reviewing risk priority number scores, 111
 - cause-and-effect matrix, 162–163
 - detection of controls, 109–111
 - occurrence of failure modes, 108–109
 - relationships, 162
 - severity of effects of failure, 107–108
 - standard deviation, 122–123
 - screening experiments, 265
 - screening measurement systems, 204
 - scrubbing, 286
 - second-order effects, 256
 - seconds², 124
 - selection, 335
 - self-healing, 60
 - service providers, 131
 - Service-Oriented Architecture (SOA), 333
 - severity scoring scale, 107–108
 - Shewhart, Walter, 290
 - shifts, 154, 192–193, 297–300
 - Shingo Prize for Operational Excellence, 354
 - short-term (σ) variation
 - calculating, 127–128
 - long-term variation and, 37–38, 131
 - min-causes, 126–127
 - overview, 125–126
 - as probability distribution, 129–130
 - quality and, 27–28
 - short-term calculations, 191–192
 - short-term capability indices (C_p), 195–196
 - short-term capability, linking to long-term performance with 1.5-sigma shift, 192–195
 - short-term data, 74
 - sigma (Z) score
 - 1.5-sigma shift, 192–195
 - overview, 189–190
 - short-term versus long-term calculations, 191–192
 - significant effects, 275–276
 - standard deviations, 190–191
 - sigma scale, 28–30
 - Σ (sum up), 120
 - σ^2 (variance), 121, 123
 - simple linear regression, 247–249, 254–255
 - simplicity, 351
 - single piece production flow, 160
 - SIPOC (Suppliers-Inputs-Process-Outputs-Controls) tool, 93–94

- Six Sigma
 - description, 9–11
 - history of, 14
 - level of quality, 189
 - universality of, 348
- Six Sigma Benchmarking Association, 354
- skewed distribution, 137–138
- slope, 149–150
- SLs (specification limits), 18–19, 191, 297
- smallest observed value (x_{MIN}),
 - 121, 142–143
- smartphones, 313
- SOA (Service-Oriented Architecture), 333
- social networks, 353–354
- societies, 354
- soft savings, 75
- Software as a Service (SaaS), 314
- sorting, 285
- SPC (statistical process control)
 - for attribute data, 305–308
 - for continuous data, 300–304
 - control charts, 291–300
 - definition, 110
 - keeping process on track, 296–297
- special cause variation, 36–37, 129, 296–300
- specification limits (SLs), 18–19, 191, 297
- specifications
 - adjusted short-term capability index,
 - 197–198
 - for characteristics, 21
 - definition, 18–19
 - Ford Motor Company example, 22
 - need for, 18
 - overview, 17–18
 - versus quality, 23–25
 - RUMBA, 19–20
 - visual inspection measurement systems, 205
- SPM (statistical process monitoring), 301
- spreadsheets
 - add-ons, 327
 - project tracking, 339
 - uses for, 316–317, 325–326
- SQL (Structured Query Language), 317
- square roots, 124
- squared effects, 256
- squaring, 122–123
- SSE (summed square error), 123, 252–253
- SSTO (total squared error), 253
- ST. *See* short-term variation
- stable and in control, 296, 298
- stable measurement systems, 202
- standard deviation
 - bell-shaped variation, 166–167
 - calculating width of variation, 121–124
 - characteristic performance distribution,
 - 190–191
 - confidence intervals
 - calculating, 239
 - overview, 234
 - variation, 235–237
 - population, 235–237
 - for process elements, 90
 - short term, 128
 - for small samples, 232
- standard normal distribution
 - calculating probability
 - above or below single value, 169
 - between or outside two values, 169–171
 - overview, 167–169
- standardization
 - belief system and, 26
 - 5S method, 286
 - of work, 99
- standards, setting and following, 289
- Start/End icon, 90
- statistical analysis tools
 - overview, 326
 - packages
 - dedicated, 327
 - JMP, 329
 - Minitab, 328
 - spreadsheet add-ons, 327
- statistical problems, 65
- statistical process control. *See* SPC
- statistical process monitoring (SPM), 301
- statistical situations, 247
- statistical solutions, 65

- statistics
 - distribution
 - measuring location, 118–120
 - overview, 117–118
 - overview, 116–117
 - variation spread
 - overview, 121
 - range, 121–122
 - standard deviation, 122–124
 - Stattek.com, 324
 - Storage icon, 90
 - straightening, 285–286
 - strength of effects, 148–150
 - Structured Query Language (SQL), 317
 - subgroups. *See also* samples
 - averages and standard deviations
 - charts, 304
 - data, 300, 302
 - p charts, 306–307
 - u charts, 307–308
 - subprocesses, 95
 - sum up (Σ), 120
 - summed square error (SSE), 123, 252–253
 - superstitious delusions, 34–35
 - suppliers, 93
 - Suppliers-Inputs-Process-Outputs-Controls (SIPOC) tool, 93–94
 - sustain element, 5S method, 286
 - sustain stage, Six Sigma, 60
 - swim lanes, 91–92
- **T** •
- T (targets), 19, 21–22
 - tables, 315
 - tablets, 313
 - Taguchi, Genichi, 24
 - Taguchi loss function, 23–25
 - take one, make one ideal, 160–161
 - takt time, 98–99
 - tampering with the process, 281
 - tangible results, 345–346
 - targets (T), 19, 21–22
 - team input
 - cause-and-effect analysis, 164
 - involving right people in project, 332
 - Lean practices, 351
 - value stream maps, 97
 - team members
 - assigning projects, 86
 - brainstorming, 102–103
 - business-case statements, 68–70
 - defining projects, 70–71
 - objective statements and, 84–85
 - project definition, 337
 - unleashing potential, 347
 - technology tools
 - analytics, 323–325
 - desktop computers
 - Microsoft Office, 316–317
 - overview, 313
 - process mapping, 317–318, 320–321
 - enterprise-class, 321
 - laptop computers, 313
 - leveraging, 347
 - for management, 14–15
 - manual tools, 314–315
 - overview, 311–312, 323
 - platforms and protocols, 312–314
 - process intelligence, 318–319
 - spreadsheets, 325–326
 - statistical analysis, 326–330
 - technology vendors, 355
 - temporal variation, 216–222
 - Texas Instruments, 324
 - themes, 66
 - thinking for breakthrough, 45–46
 - third quartile, 142
 - Thompson, William (Lord Kelvin), 116–117
 - 3-Gen approach (going to *gemba*), 98, 109, 350
 - TI-30X calculator, 324
 - TI-89 calculator, 324
 - time scales, 117–118
 - timelines, 98
 - time-series charts, 74
 - time-to-time variation, 217

- to-be state, 92
 tollgates, 44
 tool wear, 131
 tools. *See also* brainstorming tools;
 intelligence tools; project management;
 statistical analysis tools; technology tools
 intelligence, 340–342
 knowledge management, 333, 342
 learning, 333
 manual, 312–315, 324
 measurement instruments, 39
 training, 348
 top commitment, 13
 total squared error (SSTO), 253
 tracking, 335, 338–340
 traditional methods, 82–83
 training, 50, 58, 356
 Transport icon, 90
 transportation, 157
 Transportation, Waiting, Overproduction,
 Defects, Inventory, Motion, Extra
 Processing (TWO-DIME) categories, 157
 trends, 146–147, 153, 293, 300
 trial-and-error approach, 262
 trivial many, 40–41
 2^k factorial experiments
 analyzing
 effects, 270–276
 equation, 276–278
 overview, 270
 conducting
 blocking, 269
 gathering data, 269–270
 overview, 269
 randomizing, 269
 planning
 experiment factors, 266–267
 experimental codes and design matrix,
 267–268
 overview, 266
 TWO-DIME (Transportation, Waiting,
 Overproduction, Defects, Inventory,
 Motion, Extra Processing)
 categories, 157
 two-sided specifications, 19
 Type-1 corrective actions, 288
 Type-2 corrective actions, 288
- **U** •
- u* (non-conformities per unit) charts,
 292, 305
 UCLs (upper control limits), 293
 understandability, 20
 uniform distribution, 137–138
 Unisys, 54
 units, 186, 217
 upper control limits (UCLs), 293
 upper specification limits (USLs), 19, 21
 upstream, 46
- **V** •
- VA (value added) process steps, 91, 156
 value
 absolute, 128
 analyzing process flow, 160–161
 ascertaining, 156
 cause-and-effect analysis, 161–164
 customer, 155–160, 349
 Kano's framework, 158–160
 leveraging failure mode effects
 analysis, 164
 overview, 155
 potential, 76
 return on investment and, 13
 waste, 157–158
 value added (VA) process steps, 91, 156
 value stream maps (VSMs)
 custom, 96–99
 description, 350
 overview, 94
 value stream, 95–96
 value streams, 95–96
 variable (continuous) data, 113–116,
 291–292, 300–304

- variables
 - confounding, 34
 - factors, 261
 - values of, 267
 - variations. *See also* normally-shaped variation
 - average, 140
 - belief system and, 26
 - beyond expected limits, 152–153
 - calculating, 125–131
 - categorizing, 216–217
 - confidence intervals, 235–237, 239
 - connecting quality and, 27–28
 - distribution in comparative box plots, 143–144
 - entitlement, 130–131
 - Ford Motor Company example, 22
 - between group, 214–215
 - within group, 214–215
 - identifying sources of through graphical analysis, 213–215
 - location, 119
 - long-term, 128–130
 - in Measurement System Analysis, 200–203
 - mode, 138–139
 - range, 121–122, 140
 - ratio values, 207–208
 - reducing, 35–38
 - shape, 137
 - short-term, 125–128
 - sigma scale, 28–29
 - spread, 121–124
 - standard deviation, 122–124, 253
 - Vassar University, 325
 - Verification step, 81–82
 - Visio, Microsoft, 317–318
 - visual inspection measurement systems, 205
 - voice of business (VOB), 66, 93
 - voice of customer (VOC). *See also* capability breakthrough strategy, 66
 - definition, 93
 - project management, 332
 - tools, 13
 - value, 155–156
 - voice of process (VOP), 93. *See also* capability
 - VSMs. *See* value stream maps
- W ●
- waiting, 157
 - wants, 159
 - waste
 - muda-mura-muri*, 350–351
 - reducing, 99
 - TWO-DIME categories, 157–158
 - WCBF (Worldwide Conventions and Business Forums), 355
 - web searches, 353–354
 - weight, 162
 - whisker plots, 141–144
 - whiskers, 141
 - width, 195–198
 - Williams, Bruce, 349
 - within group variation, 214–215
 - within unit variation, 216–217, 220–221
 - word processors, 339
 - Worldwide Conventions and Business Forums (WCBF), 355
- X ●
- $X - R$ (averages and ranges) charts, 292, 301, 303–304
 - $X - S$ (averages and standard deviations) charts, 292, 301, 304
 - x_{MAX} (largest observed value), 121, 142–143
 - x_{MIN} (smallest observed value), 121, 142–143
- Y ●
- $Y = f(X) + \varepsilon$ (breakthrough) equation, 31–32, 277–278
 - Yellow Belts, 54, 56, 86, 352
 - yield
 - belief system and, 26
 - first time yield, 180–182
 - hidden factory, 182

linking defect rate and, 189
overview, 179–181
rolled throughput yield, 27, 180, 183–184

• Z •

Z score. *See* sigma score
Z transformation, 171–172, 173

<http://www.pbookshop.com>